

Inspection Photos

Operator: Gunnison Energy
Location/API #: 051-06103
Date: 6-18-2019



Photo 1. View of the eastern project area from the southeastern corner facing northward. Revegetation is sparse and weedy on steep cut and fill slopes.



Photo 2. View of the southern project area from the southeastern corner facing westward.