

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2019

Submitted Date:

06/28/2019

Document Number:

679704649**FIELD INSPECTION FORM**Loc ID: 335707 Inspector Name: Moran, Rick On-Site Inspection: ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 110 W 7TH STREETCity: FORTH WORTH State: TX Zip: 76102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**17 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Reid, Van		van_reid@xtoenergy.com	
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283239	WELL	PR	01/01/2019	GW	103-10698	FREEDOM UNIT 297-28A1	PR
283241	WELL	AL	05/05/2011	LO	103-10697	FREEDOM UNIT 297-28A8	AL
283242	WELL	SI	06/15/2012	GW	103-10696	FREEDOM 297-28A2	SI
283244	WELL	AL	05/05/2011	LO	103-10695	FREEDOM UNIT 297-28A9	AL
283245	WELL	PR	01/01/2019	GW	103-10694	FREEDOM UNIT 297-28A3	PR
283246	WELL	AL	05/05/2011	LO	103-10693	FREEDOM UNIT 297-28A7	AL
283248	WELL	AL	05/05/2011	LO	103-10691	FREEDOM UNIT 297-28A6	AL
283249	WELL	SI	10/01/2017	GW	103-10692	FREEDOM UNIT 297-28A4	SI
283252	WELL	PR	01/01/2019	GW	103-10690	FREEDOM UNIT 297-28A5	PR

**General Comment:**

COGCC Inspection Report Summary.

On 6-28-2019 at approximately 7:00, inspector Rick Moran, conducted a routine inspection at XTO well pad 297-28 in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) No well head sign. Photo 3. Complete by 8-26-2019.
- 2) Tear in secondary containment liner. Photo 4. Complete by 7-29-2019.
- 3) MIT

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 67970.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	No well head sign present on 297-28A4.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	08/26/2019
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-675-4177

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Chemical		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Two containers of SCI 8760 with secondary containment.		
Corrective Action:		Date:	
Type: Pig Station	# 1		

Comment:			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:	Inside building.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	400 BBLs	STEEL AST		39.852000,-108.293600	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			Inadequate
Comment:	Hole in secondary containment tank liner.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date: 07/29/2019

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 283239 Type: WELL API Number: 103-10698 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well on plunger lift.

Corrective Action:

Date:

Facility ID: 283241 Type: WELL API Number: 103-10697 Status: AL Insp. Status: AL

**Idle Well**

Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: No wellhead present.

Corrective Action:

Date:

Facility ID: 283242 Type: WELL API Number: 103-10696 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: MIT scheduled for 6-28-2019 @ 7:00 form 42 document 402076568. Inspector on location from 7:00 to 8:00. Operator was not on location for MIT.  
Last MIT on 8-4-2014.

Corrective Action:

Date:

Facility ID: 283244 Type: WELL API Number: 103-10695 Status: AL Insp. Status: AL

**Idle Well**

Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: No wellhead present.

Corrective Action:

Date:

Facility ID: 283245 Type: WELL API Number: 103-10694 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well on plunger lift.

Corrective Action:

Date:

Facility ID: 283246 Type: WELL API Number: 103-10693 Status: AL Insp. Status: AL

**Idle Well**

Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: No wellhead present.

Corrective Action:

Date:

Facility ID: 283248 Type: WELL API Number: 103-10691 Status: AL Insp. Status: AL

**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: [No wellhead present.](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 283249 Type: WELL API Number: 103-10692 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: [Last MIT on 12-7-2018.](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 283252 Type: WELL API Number: 103-10690 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well on plunger lift.](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent significant soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704650	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865188">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865188</a>