

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/24/2019

Submitted Date:

06/24/2019

Document Number:

687904973**FIELD INSPECTION FORM**

Loc ID 333764 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 13 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------|--------------|-----------------------------|------------------------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Roland, Kandis | | kroland@hilcorp.com | |
| Ray, Mandi | 505-324-5122 | mray@hilcorp.com | |
| Shorty, Priscilla | | pshorty@hilcorp.com | All SW Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 260831 | WELL | PR | 11/27/2007 | GW | 067-08513 | ARGENTA 34-10 32-4R | PR |
| 290758 | WELL | PR | 02/01/2011 | GW | 067-09369 | ARGENTA 34-10 32-4A | PR |

General Comment:

[Site inspection with photos at the end of this report.](#)

| Location | | | |
|--|---|--------|------------------|
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Sign posted at entrance to location. | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Tank labeling does not reflect current operator or have current contact/emergency information. | | |
| Corrective Action: | Update signs to reflect current operator and contact informaiton per Rule 210.d. | Date: | 07/24/2019 |
| Emergency Contact Number: | | | |
| Comment: | Location sign does not have emergency contact information/911 posted on sign. | | |
| Corrective Action: | Update sign to include emergency contact information/911 per Rule 210.e. | | Date: 07/24/2019 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | <input style="width: 100%;" type="text"/> | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | T-post and hogwire around produced water tank. | | |
| Corrective Action: | | Date: | |
| Equipment: | | | |
| Type: Flow Line | # 12 | | corrective date |
| Comment: | 2-4" flowlines from wellheads to separator. 1-1" flowline from separator to pumpjack engine fuel gas. 1-1" flowline from separator to heated produced water tank fuel gas. 2-2" flowlines from wellhead to separator. 1-2" flowline from separator dump valve to produced water tank. 2-4" flowlines from separator to meter house. 2-4" flowlines merging into 1-6" flowline from meter house to offsite dogleg. | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 2 | | |
| Comment: | PVC bradenhead access. | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 2 | | |
| Comment: | On separator and heated produced water tank. | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 2 | | |
| Comment: | Wellheads. | | |

| | | | |
|---------------------------------|-----|-------|--|
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|------------------|---------|--------|
| PRODUCED WATER | 1 | 300 BBLs | HEATED STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 260831 Type: WELL API Number: 067-08513 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Facility ID: 290758 Type: WELL API Number: 067-09369 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---|
| | | | | Material Handling And Spill Prevention | Pass | Spill prevention for engine oil day tank. |
| Ditches | Pass | | | | | |
| Berms | Pass | Compaction | Pass | | | |
| Compaction | Pass | Gravel | Pass | | | |
| Gravel | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 402086185 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4859599 |
| 687904974 | Update tank labeling. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4859590 |
| 687904975 | Missing emergency contact information. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4859591 |