

Inspection Photos

Location #334480

Operator: Fram

Inspection #: 692401123

Inspection Date: 6/21/19






Photo#1:
Overview of Location to West.

June 21, 2019




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Fram Mansur Loc#334480



Photo#2:
Existing vegetation is weedy.



Photo#3:
Existing vegetation is weedy.

June 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Fram Mansur Loc#334480



Photo#4:
Stained soil and equipment coated with oily waste.

Photo#5:
Stained soil and equipment coated with oily waste.

June 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Fram Mansur Loc#334480



Photo#6:
Unused equipment stored on site.

June 21, 2019



Photo#7:
Open Rat Hole at Well API#077-09473.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Fram Mansur Loc#334480



Photo#8:
Weeds that have become Debris have blown in & around equipment.

June 21, 2019



Photo#9:
Non E&P Waste not properly stored.



Photo#10:
Various pieces of trash/debris are scattered across
Location.

June 21, 2019

Photo#11:
Various pieces of trash/debris are scattered across
Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Fram Mansur Loc#334480