

# *Inspection Photos*

*Location #312709*

*Operator: Fram*

*Inspection #: 692401128*

*Inspection Date: 6/21/19*





Photo#1:  
Overview of Location to West.

June 21, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Fram Jensen Loc#312709





**Photo#2:**

Location is infested with desiccated (dead), as well as new growth, ruderal/debris weeds.

June 21, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Photo#3:**

Weeds are growing in and around equipment.

Inspection Photos: Fram Jensen Loc#312709





**Photo#4:**  
Access road does not have adequate Stormwater controls.

June 21, 2019



**Photo#5:**  
Access road does not have adequate Stormwater controls.





**Photo#4:**  
Repair of leak has failed.

June 21, 2019



**Photo#5:**  
Repair of leak has failed.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Fram Jensen Loc#312709