

Inspection Photos

API: 05-071-07414

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 7/1/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Vehicle ruts remain along the road which is a conveyance for stormwater erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07414 | Date: 7/1/2019

Inspection Photos



Photo 2. Vehicle ruts remain along the road which is a conveyance for stormwater erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07414 | Date: 7/1/2019

Inspection Photos



Photo 3. Vehicle ruts remain along the road which is a conveyance for stormwater erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07414 | Date: 7/1/2019

Inspection Photos



Photo 4. Facing toward pumpjack. Unused equipment remains. Pipe risers with not LO/TO are unused equipment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07414 | Date: 7/1/2019

Inspection Photos



Photo 5. Meter shed has well sign.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07414 | Date: 7/1/2019

Inspection Photos



Photo 6. Pipe risers with not LO/TO are unused equipment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07414 | Date: 7/1/2019