

# Inspection Photos

API: 05-071-07186

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 7/1/2019



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07186 | Date: 7/1/2019

## Inspection Photos



**Photo 1.** The culvert is full of sediment along the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07186 | Date: 7/1/2019



## Inspection Photos



**Photo 2.** Facing toward the location. Unused risers not LO/TO.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07186 | Date: 7/1/2019



## Inspection Photos



**Photo 3.** There is soil sloughing that occurred at the east side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07186 | Date: 7/1/2019