

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/25/2019

Submitted Date:

06/26/2019

Document Number:

688305013**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 317004      Sherman, Susan      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 35190Name of Operator: GRAYHORSE OPERATING INCAddress: 20 EAST 5TH ST STE 320City: TULSA      State: OK      Zip: 74103**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Young, Rob		rob.young@state.co.us	
Crumley, Tim	(970) 768-5658	tcrumley@comcast.net	
Ellis, Charles	(918) 382-9201	caellis@grayhorse.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
234358	WELL	PR	05/10/1965	OW	121-06469	V.A. QUERY 1	SI

**General Comment:**

Flowline Spil Inspectionl, Pumper called inspector ~7pm 6/24/2019

Submit Form 19 I

Add quntity label to produced water tank

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	quantity label for produced water tank is worn off, maintain		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-768-5659

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
PW/CO	Flow Line	>= 5 bbls	
Comment:	~5 bbls out of containment, reportable spill, E3 Solutions was on location to remove free oil and contain spill, removed stained soil. Flowline needs to be excavated yet.		
Corrective Action:	Submit electronic Form 19 I to COGCC.		Date: 06/26/2019

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:	bermed, propane, shed		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:	one heated, one enardo valve				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Location Construction**

Location ID: 234358 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Form 2A COAs:****Comment:** No COAs.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:****Comment:** \_\_\_\_\_Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_**Comment:** \_\_\_\_\_**Corrective Action:** \_\_\_\_\_ **Date:** \_\_\_\_\_**On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

--

Summary of Operator Response to Landowner Issues:

--

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

--

**Inspected Facilities**Facility ID: 234358 Type: WELL API Number: 121-06469 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Shut in for spill.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402088166	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861555">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861555</a>
688305021	Grayhorse V.A.Query 1 well sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861540">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861540</a>
688305022	Grayhorse V.A.Query 1 wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861541">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861541</a>
688305023	Grayhorse V.A.Query 1 flowline spill cleanup	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861542">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861542</a>
688305025	Grayhorse V.A.Query 1 flowline spill cleanup	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861543">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861543</a>
688305026	Grayhorse V.A.Query 1 tank battery sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861544">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861544</a>
688305027	Grayhorse V.A.Query 1 tanks	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861545">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861545</a>
688305028	Grayhorse V.A.Query 1 tanks	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861546">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861546</a>
688305029	Grayhorse V.A.Query 1 produced water tank	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861547">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861547</a>
688305030	Grayhorse V.A.Query 1 pit	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861548">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861548</a>
688305031	Grayhorse V.A.Query 1 treater	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861549">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4861549</a>