

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/21/2019

Submitted Date:

06/26/2019

Document Number:

689900922**FIELD INSPECTION FORM**

Loc ID 380995 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10299Name of Operator: KUENZLER & FLORA RESERVE COMPANYAddress: 3310 W AQUEDUCT AVECity: LITTLETON State: CO Zip: 80123**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|---------|
| | | jakeflora@kfrcorp.com | |
| | | zanekuenzler@kfrcorp.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 208320 | WELL | DG | 06/21/2019 | DA | 017-07255 | BOGENHAGEN 1 | CI |

General Comment:[Construction Inspection](#)

Location Construction

Location ID: 208320 CDP: _____

Comment: It does not appear enough topsoil was salvaged per rule 1002 b. See Attached Photos

Corrective Action: Salvage topsoil as required.

Date: 06/28/2019

Form 2A COAs:

Comment: The operator submitted 48 hour notice indicating construction would start on 6/21/2019. Inspection occurred on 6/21 and the location was already constructed and conductor was set. Operations appear to have begun prior to start date.

Corrective Action: Ensure 48 hour notice is submitted accurately.

Date: _____

Wildlife BMPs:**Comment:** _____

Corrective Action: _____

Date: _____

Stormwater:

| | | | |
|------------------|---------|------------|---------|
| Erosion BMPs | Present | Other BMPs | Present |
| SLOPE ROUGHENING | Yes | | No` |

Comments: Erosion BMPs: _____

Other BMPs: _____

Corrective Action: _____ Date: _____

Comment: Operator needs to ensure vehicles do not travel outside of the access road and location boundary per rule 1002.e.

**Corrective
Action:** _____

Date: _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------|---|
| 402088697 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4862109 |
| 689900923 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4862093 |