

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 3: UNUSED EQUIPMENT ON LOCATION (UNUSED RISER). PHOTO 4: UNUSED EQUIPMENT ON LOCATION.		
Corrective Action:	COMPLY WITH RULE 603.f. AND NTO REGARDING UNUSED RISERS.	Date:	09/26/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 89177 Type: WELL API Number: 071-06756 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: MIT PERFS FROM 846' 898' CIBP SET @ 780'
 INITIAL PRESSURE 350 PSI.
 5 MIN. PRESSURE 350 PSI.
 10 MIN. PRESSURE 350 PSI.
 15 MIN. (FINAL) PRESSURE 350 PSI.

Corrective Action: _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402088978	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4862320
695100971	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4862316