

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/21/2019

Submitted Date:

06/26/2019

Document Number:

696101053

FIELD INSPECTION FORM

Loc ID 306382 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288246	WELL	SI	04/01/2017	OW	123-24562	FOSS - USX AA 5-25	TA

General Comment:

This is a WELL & BATTERY inspection.
Well is Temporarily Abandoned (TA).
Battery: Abandoned, ALL equipment removed.
Reclamation progressing.
Abandoned Centralized Battery formerly served 2 Location IDs (306382, 310381).
(2 - wells ; Temporarily Abandoned (TA)).
Abandoned Battery GPS Coordinates SE Corner: 40.515428, -104.469150
Follow-up to Field Inspection Report Doc. #684905466 dated 05/24/2018.

Location			
Lease Road:			
	Type Access		
	comment: Adequate		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
	Type WELLHEAD		
	Comment:		
Corrective Action:			Date:
Emergency Contact Number:			
	Comment: Emergency number at wellsite is NOT valid. Refer to Rule 210.b. See photo #2		
	Corrective Action: Post valid emergency number at wellsite. Comply w/ Rule 210.b. See photo #2		Date: <u>07/26/2019</u>
Good Housekeeping:			
Type	WEEDS		
	Comment: Prior & this insp: Weed encroachment at wellsite. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. Weeds remain at wellsite. Original Corrective Action date: 06/04/2018. Remains applicable. See photos #1, 2.		
Corrective Action:	Weeds remain at wellsite from prior & this insp. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. See photos #1, 2.		Date: <u>06/04/2018</u>
Type	OTHER		
	Comment: Prior insp: Stained soil at crude oil tank loadout. Mechanical conditions. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Remove or remediate stained soil at crude oil tank loadout. Comply w/ Rule 605.d. Original Corrective Action date: 06/25/2018. This insp: * Battery has been abandoned. ALL equipment has been removed. Stained soil NOW appears mitigated. See photos #3, 4.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Removed		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Removed		
Corrective Action:			Date:

Equipment:

Type:	#		corrective date
Horizontal Heated Separator	# 0		
Comment:			
Corrective Action:			Date:
Type:	#		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 0		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 0		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Emission Control Device	# 0		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	<100 BBLS	PBV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint	
Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint	
Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:	
Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 288246 Type: WELL API Number: 123-24562 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA. Battery Abandoned. ALL equipment removed.
Last Prod: 03/2017.
SI/TA. MIT requirement waived per variance Doc #401474555. Orange decommission tag for SI/TA status present. Locked Out Tagged Out (LOTO). (NOBLE)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 06/21/2019 at approximately 16:09 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: FOSS - USX AA-66N63W /5SWSW Location ID: 306382 Location County: Weld County, Colorado Weather: Damp, from prior rain.</p> <p>While there, I observed: Well(s) - 1: Temporarily Abandoned (TA). Battery: Abandoned, ALL equipment removed. Reclamation progressing. Abandoned Centralized Battery formerly served 2 Location IDs (306382, 310381). Abandoned Battery GPS Coordinates SE Corner: 40.515428, -104.469150</p> <p>Follow-up to Field Inspection Report Doc. #684905466 dated 05/24/2018. 1 of 2 Corrective Actions appears addressed. 1.) Stained soil at crude oil tank loadout. Mechanical conditions. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Remove or remediate stained soil at crude oil tank loadout. Comply w/ Rule 605.d. Original Corrective Action date: 06/25/2018. * Battery has been abandoned. ALL equipment has been removed. Stained soil NOW appears mitigated. See photos #3, 4.</p> <p>1 of 2 Corrective Actions appears NOT addressed. 1.) Weed encroachment at wellsite. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f . Original Corrective Action date: 06/04/2018. Remains applicable. See photos #1, 2.</p> <p>1: NEW Corrective Actions observed on this inspection. 1.) Emergency number at wellsite is NOT valid. Refer to Rule 210.b. Post valid emergency number at wellsite. Comply w/ Rule 210.b. See photo #2. Corrective Action date: 07/26/2019.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	<p>evinsb</p>	<p>06/26/2019</p>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402088708	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4862117
696101054	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4862099