

Maralex Resources Inc.  
API # 05-045-09853  
Inspection # 696600237



Photo #1 Photo of Tank Battery sign on Meter

Photo #2 photo from entrance of location

Maralex Resources Inc.  
API # 05-045-09853  
Inspection # 696600237



Photo #3 photo of tank battery

Photo #4 photo of Wellhead

Maralex Resources Inc.  
API # 05-045-09853  
Inspection # 696600237



Photo #5 Weeds and Debris on location



Photo #6 Weeds and Debris on location and in tank battery containment

**Maralex Resources Inc.**  
**API # 05-045-09853**  
**Inspection # 696600237**



**Photo #7 Storm Water Erosion moving off location on East side of location**



**Photo # 8 Storm Water Erosion moving off location on South East side of location along access road, Waddle needs maintenance.**

Maralex Resources Inc.  
API # 05-045-09853  
Inspection # 696600237



**Photo #9 Storm water erosion moving off location on SE side of entrance.**



**Photo #10 Storm water erosion moving off location down access road on east entrance.**

Maralex Resources Inc.  
API # 05-045-09853  
Inspection # 696600237



**Photo #11 Storm Water Erosion moving off location on East side of location**