

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401931755

Date Received:

02/06/2019

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10261

Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLC

Address: 730 17TH ST STE 500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Greenly, Tyler</u>		<u>tgreenly@bayswater.us</u>
<u>Kaminky, Ryan</u>		<u>rkaminky@bayswater.us</u>
<u>Pesicka, Conor</u>		<u>conor.pesicka@state.co.us</u>
<u>Barbula, Don</u>		<u>dbarbula@bayswater.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696100026

Inspection Date: 01/30/2019

FIR Submit Date: 01/30/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BAYSWATER EXPLORATION & PRODUCTION LLC

Company Number: 10261

Address: 730 17TH ST STE 500

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 453331

Location Name: G & D Hanks Number: 27-N Pad County: _____

Qtrqtr: SWSE Sec: 27 Twp: 7N Range: 66W Meridian: 6

Latitude: 40.542130 Longitude: -104.759854

FACILITY - API Number: 05-123-00 Facility ID: 453331

Facility Name: G & D Hanks Number: 27-N Pad

Qtrqtr: SWSE Sec: 27 Twp: 7N Range: 66W Meridian: 6

Latitude: 40.542130 Longitude: -104.759854

CORRECTIVE ACTIONS:

1 ☒ CA# 122146

Corrective Action: Move Transfer pump to a safe distance from flowback tanks bank. Comply with Rule 606A.b.

Date: 02/06/2019

Response: CA COMPLETED

Date of Completion: 02/05/2019

One pump removed as it was not being used, the other moved 85' from flowback tanks and lines rerouted.

Operator
Comment:

COGCC Decision: Approved

COGCC Representative: Follow-up Field Inspection Report Doc #696101124 dated 07/03/2019 confirms transfer Pump w/ internal combustion engine NOW appears to have been removed from site.
Corrective Action appears addressed.

2 ☒ CA# 122147

Corrective Action: Treat and/or remove stained soil. Comply with Rule 907.e.

Date: 03/01/2019

Response: CA COMPLETED

Date of Completion: 02/01/2019

Operator Comment: All contaminated soil removed and clean soil spread.

COGCC Decision: Approved

COGCC Representative: Follow-up Field Inspection Report Doc #696101124 dated 07/03/2019 confirms Stained soil at SE corner of site NOW appears to be mitigated.
Corrective Action appears addressed.

3 ☒ CA# 122148

Corrective Action: Properly ground flowback tanks. Comply with Rule 605.c.

Date: 03/01/2019

Response: CA COMPLETED

Date of Completion: 01/31/2019

Operator Comment: All tanks grounded, and installed ground rod. Tested with Ohm meter to confirm ground.

COGCC Decision: Approved

COGCC Representative: Follow-up Field Inspection Report Doc #696101124 dated 07/03/2019 confirms East flowback tanks NOW appear removed from site. Received ohm grounding test from Operator.
Corrective Action appears addressed.

OPERATOR COMMENT AND SUBMITTAL

Comment: all corrective actions were addressed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ryan Kaminky

Signed: _____

Title: Production Manager

Date: 2/6/2019 4:00:05 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401931755	FIR RESOLUTION SUBMITTED
-----------	--------------------------

401931770	ground test gd hanks
-----------	----------------------

Total Attach: 2 Files