

Inspection Photos
Location Name: Mutual 01-17H
Location ID: 324757



Photo 1. Equipment stored on location. Site degradation.



Photo 2. Example of trash on location.



Inspection Photos
Location Name: Mutual 01-17H
Location ID: 324757



Photo 3. Example of debris on location.



Photo 4. Example of trash on location.



Inspection Photos
Location Name: Mutual 01-17H
Location ID: 324757



Photo 5. Example of stained soil on location.



Photo 6. Example of storage of cuttings remediation material.



Inspection Photos
Location Name: Mutual 01-17H
Location ID: 324757



Photo 7. Condensate tank labeled as crude oil. No liner apparent, berm not compacted.



Photo 8. Cellar full of stormwater with free product on top and stained soil around wellhead.



Inspection Photos
Location Name: Mutual 01-17H
Location ID: 324757



Photo 9. Cellar full of stormwater with free product on top and stained soil around wellhead.



Photo 10. No tracking BMPs apparent at location entrance from highway.



Inspection Photos
Location Name: Mutual 01-17H
Location ID: 324757



Photo 11. Tracking north onto Colorado Highway 14.



Photo 12. Tracking south onto Colorado Highway 14.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources