

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2019

Submitted Date:

06/26/2019

Document Number:

679704620

**FIELD INSPECTION FORM**

Loc ID 441601 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100264  
Name of Operator: XTO ENERGY INC  
Address: 110 W 7TH STREET  
City: FORTH WORTH State: TX Zip: 76102

**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	
Reid, Van		van_reid@xtoenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
441602	WELL	PR	10/27/2015	GW	103-12269	RNPU 197-15A1	PR

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 6-26-2019 at approximately 12:15, inspector Rick Moran, conducted a follow up inspection at XTO Energy well RNPU 197-15A1 in Rio Blanco county of FIR document 679702802.

The following compliance issues were identified as resolved:

- 1) Unused equipment.

Additional compliance issues were identified:

- 1) Well head sign not present. Photo 2. Complete by 8-26-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704620.

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	Lease road.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	No labels present on tanks. Smell of recent new paint on tanks. Tanks appear not currently in use. Tanks will need labels.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign not posted.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	08/26/2019

**Emergency Contact Number:**

Comment: 970-675-4117

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

**Fencing/:**

Type	LOCATION		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Emission Control Device	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tote with secondary containment.		
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 20		
Comment:	Tank trailers.		

Corrective Action:	Date:
--------------------	-------

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	400 BBLs	STEEL AST		39.863100,-108.863100

Comment:	Date:
Corrective Action:	Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			Adequate

Comment:	Date:
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	5	1000 BBLs	STEEL AST		39.863100,-108.863100

Comment:	Date:
Corrective Action:	Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	750 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			Adequate

Comment:	Date:
Corrective Action:	Date:

**Venting:**

Yes/No	NO		Date:
Comment:			
Corrective Action:	Date:		

**Flaring:**

Type		Date:
Comment:		
Corrective Action:	Date:	

**Inspected Facilities**

Facility ID: 441602 Type: WELL API Number: 103-12269 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps	Pass					
Rip Rap	Pass					

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402091434	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864559">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864559</a>
679704621	inspection photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864276">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864276</a>