

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2019

Submitted Date:

07/04/2019

Document Number:

692401134

FIELD INSPECTION FORM

Loc ID 324752 Inspector Name: Colby, Lou On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10598
 Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC
 Address: 123 ROBERT S KERR AVE
 City: OKLAHOMA CITY State: OK Zip: 73102

Findings:

- 10 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Church, Matt	405-651-6853	mchurch@sandridgeenergy.com	
		sandridgeenvironmental@sandridgeenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295294	WELL	IJ	03/01/2019	DSPW	057-06467	VANETA 1-32D	RI

General Comment:

This is an Interim Reclamation & Stormwater focused Inspection, a Follow Up to RI Inspection #692400961. Any Corrective Actions from previous Inspections that have not been addressed are still applicable. CA from Previous RI Inspection to Install or repair required BMPs per Rule 1002.f. has not been resolved.

This SWD Injection site remains very congested, experiencing a continual high volume of truck traffic. The Location is within a Sensitive Wildlife Habitat; Greater Sage Grouse. Refer to Reclamation & Stormwater sections.

Inspected Facilities

Facility ID: 295294 Type: WELL API Number: 057-06467 Status: IJ Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? **Fail**

Comment [Debris in Interim Reclamation Area.](#)

Corrective Action **Remove Debris.**

Date **07/12/2019**

Unused or unneeded equipment onsite? _____

Comment [Refer to Housekeeping FIU Insp.](#)

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? **Pass**

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? Fail Production areas stabilized ? Fail
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass
Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail
Production areas have been stabilized? Fail Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation Fail

1003e. INTERIM VEGETATION TRANSECT
TRANSECT RESULTS OF DISTURBED AREA% _____
TRANSECT RESULTS OF REFERENCE AREA% _____
TOTAL % OF DESIRABLE VEGETATION COVER _____
VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? P

Comment There are only two small areas that can be considered Interim Reclamation at the Northeast and Southern portions of site; both areas suffer from vehicle traffic incursion resulting in rutting and general degradation of these areas. The Southern area is inundated with stormwater flow from the road and pad due to absence & failure of BMPs to convey stormwater to retention pond. Refer to Photo Log attached.

Corrective Action Exclude traffic from Interim areas ASAP. Reinstall interim reclamation in two areas by 11/1/19.

Date 07/11/2019

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
TRANSECT RESULTS OF DISTURBED AREA% _____
TRANSECT RESULTS OF REFERENCE AREA% _____
TOTAL % OF DESIRABLE VEGETATION COVER _____
VEGETATIVE COVER _____

Comment:

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					Overall, lack of adequate BMPs
Ditches	Fail	Ditches	Fail			Lack of
Paving	Fail	Paving	Fail			Lack of
Retention Ponds	Fail					Lack of conveyance
Gravel	Fail					
Compaction	Fail					
		Check Dams	Fail			Lack of

Comment: Site does not have sufficient/effective BMPs to handle the high volume of traffic; rutting, sediment migration, vehicle incursion into BMPs, reclamation areas and general site degradation was observed. BMPs have not been installed to allow stabilized conveyance of stormwater to retention pond. BMPs are not installed along edges of access road, resulting in erosion & sediment migration off site. Soil stockpiles remain with no BMPs; one is pushed outside/off Location. Refer to Photo Log attached. CA Date is left at that of previous RI Inspection.

Operator has reported that stabilization of road (area of BMP concern) has been attempted with yards ++ of gravel; this does not appear to have resolved the Stormwater concerns.

Corrective Action: Install sufficient/effective BMPs in accordance with, and monitoring per Good Engineering Practices per Rule 1002.f

Date: 06/14/2019

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	295297	1433847	
	295297	1433847	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692401161	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869323