

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2019

Submitted Date:

06/28/2019

Document Number:

687905047**FIELD INSPECTION FORM**Loc ID 333992 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|---------------------------------------|
| Inspections, All | | SanJuanCOGCC@bp.com | All Inspections |
| Beebe, Sabre | 970-779-9398 | Sabre.Beebe@bpx.com | SW Inspection Reports |
| Labowskie, Steve | | steve.labowskie@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 300784 | WELL | PR | 08/02/2017 | GW | 067-09661 | UTE 01A-20 3 | PA |
| 300787 | WELL | PR | 07/30/2009 | GW | 067-09662 | UTE 01A-20 4 | PR |

General Comment:

Site inspection with photos at the end of this report.

-UTE 01A-20 3 (067-09661) Is Plugged and abandoned with dryhole marker present on location. Form 6 Document# 401773032 submitted on 9/24/18 with expiration date of 4/9/2019.

LocationOverall Good: ☐

| | | | |
|----------------------|--------------------------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Sign posted at entrance to location. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|-------------------------------------|-------|--|
| Emergency Contact Number: | | | |
| Comment: | Contact information posted on sign. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|------------------|
| Good Housekeeping: | | | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | UTE 01A-20 3 production equipment onsite. Dry hole marker already established. equipment is unused including flowlines, pumpjack, horsehead, wellhead piping, VFD drivers for electric motor. | | |
| Corrective Action: | Remove unused equipment from location per Rule 603.f. | | Date: 09/28/2019 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|---------------------------|--------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bird Protectors | # 1 | | |
| Comment: | On produced water tank vent. | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 2 | | |
| Comment: | Electric VFD driven motors. | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | PVC bradenhead access. | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead and 1 dryhole marker. | | |
| Corrective Action: | | Date: | |

| | | |
|---------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|
| Type: Gas Meter Run | # 2 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Flow Line | # 6 | |
| Comment: | 1-4" disconnected flowline from PA well to separator that needs to be cut/capped. 1-4" flowline from producing wellhead to separator. 1-2" flowline from separator dump valve to produced water tank. 1-2" flowline from produced water tank pumping unit to offsite produced water gathering system. 2-4" flowlines from separator to offsite dogleg. | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|-----------|-----------|---------|--------|
| PRODUCED WATER | 1 | <100 BBLS | PBV STEEL | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 300784 | Type: | WELL | API Number: | 067-09661 | Status: | PR | Insp. Status: | PA |
| Facility ID: | 300787 | Type: | WELL | API Number: | 067-09662 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |
| Compaction | Pass | Compaction | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 402091855 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865148 |
| 687905048 | Dryhole Marker/Unused equipment. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865108 |
| 687905049 | Unused equipment/piping/flowlines | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865109 |
| 687905050 | Unused equipment. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865110 |