

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2019

Submitted Date:

06/28/2019

Document Number:

687905051**FIELD INSPECTION FORM**Loc ID 325655 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215175	WELL	PR	02/13/1986	GW	067-06780	UTE 01A-20 2	PR

**General Comment:**[Site inspection with photos at the end of this report.](#)

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign posted at entrance to location is missing letters and numbers and cant be read.		
Corrective Action:	Rapair or replace sign per Rule 210.	Date:	07/28/2019

Emergency Contact Number:			
Comment:	Emergency contact information not legible. Update contact information on sign at entrance to location.		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Cattle panels around wellhead and pumpjack.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 5		
Comment:	1-3" flowline from wellhead to separator. 1-1" flowline from separator to pumpjack engine fuel gas. 1-3" flowline from separator to meter house. 1-2" flowline from separator dump valve to offsite produced water gathering system. 1-3" flowline from meter house to offsite dogleg.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	Natural gas engine on pumpjack. Engine exhaust muffler has approx. 3' x 5' area of stained soil and gravel from exhaust leak.		
Corrective Action:	Clean up stained soil/gravel to comply with Rule 907.e.		Date: 07/28/2019
Type: Bird Protectors	# 1		
Comment:	On separator stack.		
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	215175	Type:	WELL	API Number:	067-06780	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402091856	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865149">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865149</a>
687905052	Repair/replace sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865111">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865111</a>
687905053	Engine exhaust stained soil/gravel	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865112">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865112</a>