

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/06/2019

Submitted Date:

06/28/2019

Document Number:

688800550

**FIELD INSPECTION FORM**

Loc ID 324469 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 77330  
Name of Operator: SG INTERESTS I LTD  
Address: 100 WAUGH DR SUITE 400  
City: HOUSTON State: TX Zip: 77007

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 16 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		inspection@sginterests.com	<a href="#">All Inspections</a>
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271432	WELL	PR	02/01/2011	GW	051-06057	FEDERAL 11-90-24 1	EI
459028	SPILL OR RELEASE	AC			-	24-1 Can N/A	EI

**General Comment:**

On June 6, 2019 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the SG Interests Federal 11-90-24 #1. For the most recent field inspection report of this facility, please refer to document #688800520. This site visit was conducted to document the progress of Remediation Project #12222.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign mounted to stock panels near well head.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Sign posted near separator.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	ASTs are labeled with contents, capacity, and NFPA placards.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Lube Oil	Pump Jack	<= 1 bbl	
Comment:	Concrete foundation for pump jack and surrounding gravel is stained.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 07/28/2019
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Fencing around separator and tank battery.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Partial stock panel enclosure around well head.		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Prime Mover	# 1		corrective date
Comment:	Natural gas powered.		
Corrective Action:		Date:	

Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:	Separator/meter run combo unit.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Transfer pump within secondary containment berm for tank battery.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLs	HEATED STEEL AST		39.085436,-107.393067
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Lined steel ring.			
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 271432 Type: WELL API Number: 051-06057 Status: PR Insp. Status: EI

Facility ID: 459028 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Environmental**

**Spill/Remediation:**

Comment: [See REM #12222 for more information regarding this project.](#)

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	In Process					
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On June 6, 2019 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the SG Interests Federal 11-90-24 #1. For the most recent field inspection report of this facility, please refer to document #688800520. This site visit was conducted to document the progress of Remediation Project #12222.</p> <p>The impacted material from REM #12222 that was temporarily stored on the well pad has been removed.</p> <p>The excavated area has been backfilled and re-contoured. Ensure that appropriate BMPs are installed to stabilize the project area.</p>	hughesjo	06/28/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402091860	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865155">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865155</a>
688800551	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865136">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865136</a>