

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/06/2019

Submitted Date:

06/28/2019

Document Number:

688800556**FIELD INSPECTION FORM**Loc ID 324473 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 100 WAUGH DR SUITE 400City: HOUSTON State: TX Zip: 77007**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Heil, John		john.heil@state.co.us	
Inspections, All		inspection@sginterests.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276658	WELL	PR	09/01/2018	GW	051-06061	FALCON SEABOARD 11-90-11 2	EI

**General Comment:**

On June 6, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests Falcon Seaboard 11-90-11 #2. For the most recent field inspection report of this facility, please refer to document #689401630.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Chemical injection container is not labeled.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	08/28/2019
Type	TANK LABELS/PLACARDS		
Comment:	ASTs are labeled with capacity, contents, and have NFPA placards.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well head sign found down in cellar.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Chemical injection system not in use.		
Corrective Action:	Comply with Rule 603.f	Date:	07/29/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Water transfer pump.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	Natural gas powered.		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	NE marker is down.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLS	HEATED STEEL AST		39.110180,-107.409595	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Lined steel containment ring.			
Corrective Action:				
		Date:		

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	276658	Type:	WELL	API Number:	051-06061	Status:	PR	Insp. Status:	EI

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for chemical container.
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On June 6, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests Falcon Seaboard 11-90-11 #2. For the most recent field inspection report of this facility, please refer to document #689401630. The well sign was found down in the cellar during this inspection. An unused/unlabeled chemical injection system is on location near the pump jack. The northeast rig anchor marker has been knocked over.	hughesjo	06/28/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402091866	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865157">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865157</a>
688800557	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865143">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865143</a>