

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/06/2019

Submitted Date:

06/28/2019

Document Number:

688800560**FIELD INSPECTION FORM**Loc ID 311728 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 100 WAUGH DR SUITE 400City: HOUSTON State: TX Zip: 77007**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Heil, John		john.heil@state.co.us	
Inspections, All		inspection@sginterests.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262657	WELL	PR	06/25/2013	GW	051-06047	FALCON SEABOARD 11-90-12 1	EI
283607	WELL	PR		GW	051-06070	FALCON SEABOARD 11-90-12 #1A	EI

General Comment:

On June 6, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests Falcon Seaboard 11-90-12 #1 and #1A. For the most recent field inspection report of this facility, please refer to document #680602930.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Chemical injection system containers have illegible labels.		
Corrective Action:	Comply with Rule 210.d.	Date:	08/28/2019
Type	WELLHEAD		
Comment:	Signs near well heads.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	ASTs have NFPA placards and are labeled with capacity and contents.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Tank battery sign for #1 and #1A.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Posted on location signs.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Fences around both well heads.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Post and wire perimeter fencing.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Fence around meter run and separator.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	HEATED STEEL AST		39.117675,-107.402761
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	STEEL AST		39.117675,-107.402761
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		
Corrective Action:		Date: <input type="text"/>
<u>Venting:</u>		
Yes/No		
Comment:		
Corrective Action:		Date: <input type="text"/>
<u>Flaring:</u>		
Type		
Comment:		
Corrective Action:		Date: <input type="text"/>

Inspected Facilities				
Facility ID: 262657	Type: WELL	API Number: 051-06047	Status: PR	Insp. Status: EI
Facility ID: 283607	Type: WELL	API Number: 051-06070	Status: PR	Insp. Status: EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for chemical containers.

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On June 6, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests Falcon Seaboard 11-90-12 #1 and #1A. For the most recent field inspection report of this facility, please refer to document #680602930. The chemical injection system containers have labels that are illegible. The well head signs are becoming illegible.	hughesjo	06/28/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402091871	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865159
688800561	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865145