

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2019

Submitted Date:

06/28/2019

Document Number:

696300297**FIELD INSPECTION FORM**
 Loc ID 426749 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426750	WELL	SI	08/01/2018	OW	123-34772	DYER USX AB 35-67-1HN	SI
426753	WELL	SI	08/01/2018	OW	123-34773	DYER USX AB 35-68-1HN	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate (x2)		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused Pneumatic Injection Pumps in East Engine house (35-67-1HN), see photos 5 & 6		
Corrective Action:	Comply with Rule 603.f .	Date:	07/31/2019
Type	TRASH		
Comment:	Trash in the Southwest corner in the West Engine house (35-68-1HN), See photo #7		
Corrective Action:	Comply with Rule 603.f .	Date:	07/31/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused chemical drum in West Engine house, along the north wall, see photo #8.		
Corrective Action:	Comply with Rule 603.f .	Date:	07/31/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 2		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

Type: Ancillary equipment	# 1	
Comment:	Chemical Tank/Pump at wellheads	
Corrective Action:		Date:
Type: Bird Protectors	# 7	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment:	Sand Traps	
Corrective Action:		Date:
Type: Prime Mover	# 2	
Comment:	Arrow Engines inside housing units for Pumping Units	
Corrective Action:		Date:
Type: Emission Control Device	# 3	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 2	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 4	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with Crude Oil Tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	2	OTHER	PBV CONCRETE		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	60	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	300 BBLs	STEEL AST		40.536710,-104.528980
Comment:					
Corrective Action:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			

Flaring:

Type			
Comment:			
Corrective Action:			

Inspected FacilitiesFacility ID: 426750 Type: WELL API Number: 123-34772 Status: SI Insp. Status: SI**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 426753 Type: WELL API Number: 123-34773 Status: SI Insp. Status: SI**Producing Well**Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday 06/28/2019 at approximately 10:00 AM, I, Inspector Erica Petrie, conducted a Field Inspection at Noble Energy INC. Dyer USX AB 35-68-1HN, at Location #426749 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused Pneumatic Injection Pumps in East Engine House, See photo #5 & #6, Comply with Rule 603.f. Corrective Action Date of 07.31.2019</p> <p>Trash in West Engine House, See photo #7, Comply with Rule 603.f. Corrective Action Date of 07.31.2019</p> <p>Unused chemical drum in West Engine house on the North wall, see Photo #8, Comply with Rule 603.f. Corrective Action Date 07.31.2019</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	petrie	06/28/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402091568	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864760
696300303	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864758