

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2019

Submitted Date:

06/28/2019

Document Number:

696600222**FIELD INSPECTION FORM**Loc ID 312658 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments4 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ried, Jordan	970-563-400	maralextechjr@gmail.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Graves, Jim		mrinc20@qwestoffice.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222099	WELL	PR	09/09/1997	GW	077-08701	SULFUR GULCH 9-98-1 1	PR

General Comment:

This is a follow up inspection from Doc# 675002022 .Dated 3/18/19 Required Corrective Action (s) items noted in previous inspections have not been satisfied.

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Corrective action made		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No battery sign		
Corrective Action:	Install sign to comply with Rule 210.b	Date:	07/29/2019

Emergency Contact Number:

Comment: 970-858-8550 / 911
Posted on Wellhead sign

Corrective Action:

Date:

Good Housekeeping:

Type	TRASH		
Comment:	Trash and Debris on location		
Corrective Action:	Comply with Rule 603.f .	Date:	07/01/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 0		

Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Tank Berm need maintenance.			
Corrective Action:	Inadequate berms around tank(s)			Date: 07/29/2019

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	222099	Type:	WELL	API Number:	077-08701	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Compaction	Pass			

Comment: Stormwater erosion not being controlled on the location at this time.
BMP's not in place, need repaired or are not being maintained at this time.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 07/29/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On (Friday) (6/28/19) at approximately (1403), I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Re-Inspection) at (Maralex) (Sulfer Gulch 9-98-1 1), (API #077-08701) in (Mesa) Colorado. While there, I observed (A Production Operation only.) During this inspection compliance issues were observed: Trash and debris on location Tank Berm needs maintenancer Stormwater erosion not being controlled on the location at this time. BMP's not in place, need repaired or are not being maintained at this time. (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	06/28/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402091873	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865161
696600227	Inspection 696600222 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4865127