

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/11/2019

Submitted Date:

06/28/2019

Document Number:

698100018**FIELD INSPECTION FORM**Loc ID 323851 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments7 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
,		dnr_cogccenforcement@state.co.us	
,	970-563-4000	maralextech@gmail.com	All Inspections
Longworth, Mike		mike.longworth@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210985	WELL	SI	07/01/2014	GW	045-06743	SOUTH SHALE RIDGE 10-7	EI

**General Comment:**COGCC Environmental inspection of tank battery, separator, and pumping unit/wellhead.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Uncontrolled weeds throughout location, including inside of tank berm, near pump jack, and at heated separator. See photos.		
Corrective Action:	Comply with Rule 603.f .		Date: 07/08/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Lube Oil	Pump Jack	<= 1 bbl		
Comment:	Accumulation of lube oil and oil-stained soil beneath prime mover. See photos.			
Corrective Action:	Remove and properly dispose of non-E&P waste, per Rule 907A.			Date: 07/28/2019
PW/CO	Tank	<= 1 bbl		
Comment:	Historical accumulations of oil-stained soil at truck loadout. See photos.			
Corrective Action:	Remove and properly dispose of oily waste, per Rule 907.e.			Date: 07/28/2019

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>				corrective date
Type: Flow Line	# 2			
Comment:	Unused flowline risers near heated separator are not locked out/tagged out.			
Corrective Action:	Comply with Rule 603.f, Lock-out & tag out unused flowline risers within 24 hours of submittal of this Field Inspection Report., remove flowline riser within 30 days.			Date: 06/29/2019
Type: Pump Jack	# 1			
Comment:	Accumulation of lube oil and oil-stained soil beneath prime mover. See photos.			
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.			Date: 07/28/2019

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:	Historical accumulations of oil-stained soil at truck loadout. See photos.					
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: 07/28/2019	

**Paint**

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	

Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient		Inadequate	
Comment: Earthen berm eroded. Vegetation growth inside of bermed area. See photos.					
Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).					Date: 07/28/2019
<b>Venting:</b>					
Yes/No					
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**Facility ID: 210985 Type: WELL API Number: 045-06743 Status: SI Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402091462	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864585">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864585</a>
698100028	20190611 Field Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864355">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4864355</a>