

Inspection Photos
Location Name: Evans 0780 21
Location ID: 438250



Photo 1. Access road with fresh material and no stormwater BMPs.



Photo 2. Access road with fresh material and no stormwater BMPs.



Inspection Photos
Location Name: Evans 0780 21
Location ID: 438250



Photo 3. Example of cuttings on location.



Photo 4. Condensate tank labeled as crude oil.

Inspection Photos
Location Name: Evans 0780 21
Location ID: 438250



Photo 5. Drip at separator with rag held in place with rock beneath drip.



Photo 6. Close up of photo 5.



Inspection Photos
Location Name: Evans 0780 21
Location ID: 438250



Photo 7. Example of additional drips on location.



Photo 8. Stained soil at wellhead, oily rags and trash at wellhead.

Inspection Photos
Location Name: Evans 0780 21
Location ID: 438250



Photo 9. Stained soil at wellheads, oil rags and trash and wellheads.



Photo 10. Trash and debris, stormwater with a sheen in cellar.

Inspection Photos
Location Name: Evans 0780 21
Location ID: 438250



Photo 11. Free product at wellhead.



Photo 12. Example of soil piles, cuttings piles, trash and debris, site degradation.

Inspection Photos
Location Name: Evans 0780 21
Location ID: 438250



Photo 13. Debris migrating off location.



Photo 14. Perimeter berm on southeast corner of location has been compromised.