

**Inspection Photos**  
**Operator: SG Interests**  
**Location/API #: 051-06110**  
**Date: 6-18-2019**



Photo 1. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing, however stability issues from cracking observed in fill slope. (see photos 4-6)





Photo 2. View of the northern project area from the northeastern project area facing westward.





Photo 3. View of soil cracking up to 10 inches deep within the northern berm.





Photo 4. View of more soil cracking within the well pad berm.





Photo 5. View of cracking within the eastern well pad berm.





Photo 6. View of area in the northwestern project area where soils are not stabilized and erosion is occurring as stormwater flows north from the project area.





Photo 7. View of cobble velocity checks along the northwestern access road. These are not sufficient as erosional down-cutting from high velocity flows, and sediment deposition where flows settle, is evident.