

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2019

Submitted Date:

07/07/2019

Document Number:

698600016

FIELD INSPECTION FORM

Loc ID 317043 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10352
Name of Operator: CM PRODUCTION LLC
Address: 390 UNION BLVD SUITE 620
City: LAKEWOOD State: CO Zip: 80228

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
234897	WELL	PR	01/02/1996	OW	121-07039	OLIVER-WARREN 1	TA

General Comment:

This is an orphaned well inspection. Inspection completed to document progress and completion of equipment decommissioning and removal.

Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

See link at end of report for path to downloadable pictures.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	HEATED STEEL AST		,
Comment:	Remove entry hatch on P3 and finish pressure washing interior of tank. Prep P2 entry hatch to remove heater flame tube and pressure wash tank interior. Not completed.				
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:			
			Date:

Flaring:

Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:			
			Date:

Inspected Facilities

Facility ID: 234897 Type: WELL API Number: 121-07039 Status: PR Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is an Orphaned Well Program well. Flow line disconnected from wellhead. Valves at wellhead are closed and bull plugs installed. Equipment decommissioning, removal and salvage is in progress.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>The CM Production Oliver Warren site equipment decommissioning, removal and salvage task is under way. The Oliver Warren site is the production facility for (1) remote well. Facility consist of (4) 300 BBL tanks, vertical separator with metal shed, and water/oil flow lines/risers. The remote wellhead has a pumping unit with electric prime mover and associated electrical supply equipment.</p> <p>Work at site today focused on continuing to clean oil production tanks. The entry hatch was removed from P3 to finish pressure washing tank interior. The entry hatch and flame tube were prepped for removal on P2 to allow interior of tank access for pressure washing. The entry hatch for both tanks were reinstalled for overnight protection. Cleaning of P3 is complete. Pressure washing P2 was not completed.</p>	stjohnw	07/07/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600017	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4870132