

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/05/2019

Submitted Date:

07/07/2019

Document Number:

698600018**FIELD INSPECTION FORM**Loc ID 317369 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10352Name of Operator: CM PRODUCTION LLCAddress: 390 UNION BLVD SUITE 620City: LAKEWOOD State: CO Zip: 80228**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270438	WELL	SI	01/29/2014	OW	121-10714	CANNON 33-24	TA

General Comment:

This is an orphaned well inspection. Inspection completed to document progress and completion of equipment decommissioning and removal.

Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

See link at end of report for path to downloadable pictures.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type PUMP JACK

Comment: Remove steel safety barrier for loading and removal.

Corrective Action:

Date:

Equipment:

corrective date

Type: Prime Mover

0

Comment: Prime mover removed and laid down for loading and removal.

Corrective Action:

Date:

Type: Pump Jack

0

Comment: Pumping unit disassembled for loading and removal. Horsehead and walking beam removed. A-Frame cut away and laid down. Counter weights removed to decrease weight of pumping unit base. Pumping unit base was cut into (3) sections for loading and removal.

Corrective Action:

Date:

Type: Flow Line

0

Comment: Wellhead
The flow line at wellhead was excavated and cement plugged and abandoned.GPS at wellhead.
40.1579921/-102.831980
GPS at manifold end point.
40.123236/-102.794673

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: Wellhead. Wellhead tree has been removed and outlet valves closed with bull plugs installed.

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 270438 Type: WELL API Number: 121-10714 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Well is an Orphaned Well Program well. Flow line disconnected from wellhead. Valves at wellhead are closed and bull plugs installed. Equipment decommissioning, removal and salvage is in progress.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
The CM Production Cannon Site equipment decommissioning, removal and salvage task is under way. The Cannon site is the production facilities for (4) remote wells. The Cannon 33-24 is one of the remote wells.	stjohnw	07/07/2019
Work on the remote wellhead location consisted of disassembly of the pumping unit. The horsehead and walking beam were removed. The A-frame was cut off pumping unit base and laid down. Counter weights were removed to decrease weight of pumping unit base. The pumping unit base was cut into (3) sections for loading. Unit is ready for haul off and removal. The wellhead flow line that ran to the well manifold on the production facility was excavated and cement plugged and abandoned. Cement plugged end at wellhead GPS is 40.1579921/-102.831980. GPS at manifold end point is 40.123236/-102794673.		

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600019	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4870134