

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/06/2019

Submitted Date:

07/07/2019

Document Number:

698600020**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection
317369 _____ St John, William (Cal) _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10352Name of Operator: CM PRODUCTION LLCAddress: 390 UNION BLVD SUITE 620City: LAKEWOOD State: CO Zip: 80228**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270438	WELL	SI	01/29/2014	OW	121-10714	CANNON 33-24	TA

General Comment:

This is an orphaned well inspection. Inspection completed to document progress and completion of equipment decommissioning and removal.

Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

See link at end of report for path to downloadable pictures.

Inspected Facilities

Facility ID: 270438 Type: WELL API Number: 121-10714 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is an Orphaned Well Program well. Flow line disconnected from wellhead. Valves at wellhead are closed and bull plugs installed. Equipment decommissioning, removal and salvage is in progress.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
The CM Production Cannon Site equipment decommissioning, removal and salvage task is under way. The Cannon site is the production facilities for (4) remote wells. The Cannon 33-24 is one of the remote wells.	stjohnw	07/07/2019
Work on the remote wellhead location consisted of loading pumping unit and associated parts on flatbed trailer for haul off. The loading work then moved to the production facility where the concrete (busted up sump) and wood debris were loaded on a side dump for haul off. Waste manifest OGC19602.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600021	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4870136