

Inspection Photos
Operator: SG Interests
Location/API #: 051-06084
Date: 6-19-2019



Photo 1. View of unused pipe within the southeastern project area.



Photo 2. View of more unused pipe stored in the northeastern project area.



Photo 3. View of deceased animal within the well cellar.



Photo 4. View of erosional channeling along the access road.



Photo 5. View of silt trap that is full of sediment and not stabilized. Culvert is installed above grade.



Photo 6. View of erosional down-cutting near the beginning of the access road.