

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2019

Submitted Date:

07/08/2019

Document Number:

696101131**FIELD INSPECTION FORM**Loc ID 416867 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		cogccinspections@gwogco.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416869	WELL	PR	03/01/2019	OW	123-31499	HCW 24-24	SI

**General Comment:**

This is a WELL & BATTERY Inspection.  
Well is Shut-In | SI.  
Battery & ALL equipment is Shut-down.  
Centralized Battery serves 4 Location IDs (416867, 416870, 416873, 428960).  
Follow-up to Field Inspection Report Doc. #696100924 dated 05/22/2019.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	<p>Prior insp: Metal tank on rack with drip containment at Battery site NOT labeled or identified. Refer to Rule 210.d for guidance. Post contents, capacity, NFPA label. Original Corrective Action Date: 04/30/2019.</p> <p>This insp: * Metal tank on rack with drip containment at Battery site NOT labeled or identified, NOW removed from site. See photos #3, 4.</p>		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Surrounded by earth berms.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel		

Corrective Action:		Date:	
<b>Equipment:</b>		corrective date	
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment: Controls crude oil tanks VOCs Pilots: OFF   Shut-down.			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment: 1 - ECD scrubber 1- Chemical drum (plastic) w/ drip containment (Placarded). Biocide.			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment: Appears plumbed to surface.			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment: Centralized Battery serves 4 Location IDs (416867, 416870, 416873, 428960).					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)	150 Bbls.				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berms w/ condensate tanks.			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	8	300 BBLS	STEEL AST		40.464737,-104.842076
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berms w/ produced H2O vault.			
Corrective Action:				
				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
			Date:

Flaring:

Type			
Comment:			
Corrective Action:			
			Date:

Inspected Facilities									
Facility ID:	416869	Type:	WELL	API Number:	123-31499	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder: PRODUCTION RECORDS			
Comment:		<div>Shut-In   SI. Production valves are shut. COGCC records indicate Last PR: 03/2019.</div>							
Corrective Action:		<div></div>					Date:		

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On MON 07/08/2019 at approximately 14:03 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: GREAT WESTERN OPERATING COMPANY LLC  Location Name: HCW /24-24  Location ID: 416867  Location County: Weld County, Colorado  Weather: Damp from prior rain.</p> <p>While there, I observed: Well(s) - 1: Well is Shut-In   SI.  Battery &amp; ALL equipment is Shut-down.  Centralized Battery serves 4 Location IDs (416867, 416870, 416873, 428960).</p> <p>Follow-up to Field Inspection Report Doc. #696100924 dated 05/22/2019.  1 of 1: Corrective Actions appears addressed.  1.) Metal tank on rack with drip containment at Battery site NOT labeled or identified.  Refer to Rule 210.d for guidance. Post contents, capacity, NFPA label.  Original Corrective Action Date: 04/30/2019.  * Metal tank on rack with drip containment at Battery site NOT labeled or identified, NOW removed from site.  See photos #3, 4.</p> <p>NO: New Corrective Actions observed on this Field Inspection Report.</p> <p>This is a summary of the inspection report.</p>	evinsb	07/08/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101132	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871426">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871426</a>