

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/03/2019

Submitted Date:

07/02/2019

Document Number:

689802797**FIELD INSPECTION FORM**Loc ID 451938 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Colby, Lou		lou.colby@state.co.us	
Inspections, General		sandridgeenvironmental@san dridgeenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451939	WELL	PR	04/18/2018		057-06602	Beaver Creek 0881 1-3H34	PR

**General Comment:****COGCC Inspection Report 689802797 Summary**

On Monday 6/03/2019 at approximately 11:30, I, Inspector Emily Waldron, conducted a field inspection at Sandridge Exploration & Production LLC Beaver Creek 0881 1-3H34, at 451938 in Jackson County Colorado.

While there, I observed Production.

During this inspection the following possible compliance issues were observed:

Non-reportable spill - stained soil at wellhead and on location. See photos 2 and 3. Comply with Rule 603.f and securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d by 8/2/2019.

Triplex jet pump no longer in use remains on location. See photo 4. Comply with Rule 603.f by 10/2/2019.

All stormwater BMPs need maintenance. Sediment migration observed, secondary containments full of stormwater. See photos 3 and 4. Install or repair required BMPs per Rule 1002.f by 8/2/2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 689802797.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 405-429-5974

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Non-reportable spill - stained soil at wellhead and on location.		
Corrective Action:	Comply with Rule 603.f . Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	08/02/2019
Type	UNUSED EQUIPMENT		
Comment:	Triplex jet pump no longer in use remains on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	10/02/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	451939	Type:	WELL	API Number:	057-06602	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
		Gravel				
Berms				Material Handling And Spill Prevention		
		Compaction				
Compaction						
Ditches						
Culverts						

Comment: [Site degradation occurring. All location stormwater BMPs need maintenance. Sediment migration observed, secondary containments full of stormwater.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 08/02/2019

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402094401	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4867345">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4867345</a>
689802856	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4867320">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4867320</a>