

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2019

Submitted Date:

07/02/2019

Document Number:

689802867

**FIELD INSPECTION FORM**

Loc ID 449274 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10598  
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC  
Address: 123 ROBERT S KERR AVE  
City: OKLAHOMA CITY State: OK Zip: 73102

**Findings:**

- 10 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Arthur, Denise		denise.arthur@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Colby, Lou		lou.colby@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	
Inspections, General		sandrIDGEenvironmental@san dridgeenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449275	WELL	PR	06/01/2018		057-06598	REU 0681 1-23H2	PR

**General Comment:**

[COGCC Inspection Report 689802867 Summary](#)  
On Wednesday 6/26/2019 at approximately 10:15, I, Inspector Emily Waldron, and Inspector Lou Colby conducted a joint field/stormwater/reclamation inspection at Sandridge Exploration & Production LLC Rabbit Ears 0681 23 449274 in Jackson County Colorado.  
While there, we observed production.  
During this inspection the following possible compliance issues were observed:  
Frack sand mentioned in inspection from 11/1/2018 document number 689801879 appears to still be on location. See photos 2-4. If spilled, released or dumped onto ground surface follow material handling and guidance per MSDS or product data sheet. Submit document, procedures, and waste disposal manifest to COGCC field inspector by 11/8/2018.  
Tubing stored on location adjacent to pump jack. See photo 1. Comply with Rule 603.f by 8/2/2019.  
Stormwater in berm. Loadout hose resting in stormwater. See photo 5. Install or repair required BMPs per Rule 1002.f by 8/2/2019.  
Washout of access road observed on 5/3/2019 document number 689802625 appears to have had gravel added to roadway, no additional BMPs observed during this inspection. No additional vehicle tracking measures observed. Tracking onto Colorado State Highway 14 is continuing. Site degradation occurring. All location stormwater BMPs need maintenance. See photos 6-9. Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.(2)F. If material is tracked onto County or public roads, contact the appropriate authority. Install or repair required BMPs per Rule 1002.f. Install or repair required BMPs per Rule 1002.f by 5/6/2019.  
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report 689802867.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	405-429-5974		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Frack sand mentioned in inspection from 11/1/2018 document number 689801879 appears to still be on location.		
Corrective Action:	If spilled, released or dumped onto ground surface follow material handling and guidance per MSDS or product data sheet. Submit document, procedures, and waste disposal manifest to COGCC field inspector.	Date:	11/08/2018
Type	STORAGE OF SUPL		
Comment:	Tubing stored on location adjacent to pump jack.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/02/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flare	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	#		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	OTHER	STEEL AST		,
Comment:	675 BBL capacity				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			Inadequate
Comment:	Stormwater in berm. Loadout hose resting in stormwater.			
Corrective Action:	Install or repair required BMPs per Rule 1002.f.			Date: 08/02/2019

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	OTHER	STEEL AST		,
Comment:	675 BBL capacity				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			Inadequate
Comment:	Stormwater in berm. Loadout hose resting in stormwater.			
Corrective Action:	Install or repair required BMPs per Rule 1002.f.			Date: 08/02/2019

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 449275 Type: WELL API Number: 057-06598 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

**Comment:** Washout of access road observed on 5/3/2019 document number 689802625 appears to have had gravel added to roadway, no additional BMPs observed during this inspection. No additional vehicle tracking measures observed. Tracking onto Colorado State Highway 14 is continuing. Site degradation occurring. All location stormwater BMPs need maintenance.

**Corrective Action:** Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.(2)F. If material is tracked onto County or public roads, contact the appropriate authority. Install or repair required BMPs per Rule 1002.f.

Date: 05/06/2019

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402094765	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4867534">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4867534</a>
689802868	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4867532">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4867532</a>