

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/01/2019

Submitted Date:

07/02/2019

Document Number:

689900948**FIELD INSPECTION FORM**
 Loc ID 307317 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 6295 GREENWOOD PLAZA BLVD #100City: GREENWOOD State: CO Zip: 8111-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|----------------------------|---------|
| | | ediefitzgerald@tcenergy.us | |
| Mack, Ronald | | ronaldmack@tcenergy.us | |
| | | robfoos@tcenergyllc.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 217446 | WELL | PR | 10/01/1996 | GW | 071-06223 | APACHE CANYON 20-1 | RI |

General Comment:

This is a Stormwater inspection.

This is a follow up to the previous inspection #689900773.

Corrective actions of the previous inspection have not been performed.

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: The main road in The Southfork has areas of road damage (potholes) causing vehicles to widen the road. The road needs to be graded and maintained. There is erosion occurring off the northeast side of the pad. Sediment is accumulating near the culvert of the access road. The corrective action of the previous inspection has not been performed. Previous corrective action date remains for possible enforcement. Corrective action needs to be performed immediately. See Attached Photos

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 07/01/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402094898 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4867605 |
| 689900949 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4867586 |