

Inspection Photos
Operator: SG Interests
Location/API #: 051-06113
Date: 6-19-2019



Photo 1. View of the eastern project area from the northeastern corner facing southward. Blanketing is torn and erosion is continuing.



Photo 2. Another view of the eastern cut-slope with exposed soils and torn erosion control blanket.



Photo 3. View of wellhead and unused/stored equipment within the project area. Ponding is occurring on well pad.



Photo 4. View of culvert and bare soils along the access road. Culvert is full of sediment and bare soils are not stabilized. Erosion is occurring within the roadside ditch.



Photo 5. View of armoured culvert outlet along the access road facing downslope. Sediment in the foreground and on rocks is deposited from the culvert outlet. A perennial stream flows down-slope in the background.



Photo 6. View of bare soils on down-slope side of access road. Bare soils are eroding downslope into the stream.



Photo 7. View of another culvert inlet along the access road. Culvert is full, drainage and loose soils on side slopes are not stabilized.



Photo 8. Another view of loose soils along the access road where soils are actively eroding downslope into the adjacent perennial stream.