

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2019

Submitted Date:

07/03/2019

Document Number:

689802876

FIELD INSPECTION FORM

Loc ID 451456 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10598
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC
Address: 123 ROBERT S KERR AVE
City: OKLAHOMA CITY State: OK Zip: 73102

Findings:

- 7 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Colby, Lou		lou.colby@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	
Inspections, General		sandridgeenvironmental@sandridgeenergy.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	
Arthur, Denise		denise.arthur@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451455	WELL	PR	08/16/2018		057-06601	Mallard 0780 1-15H22	SI

General Comment:

[COGCC Inspection Report 689802876 Summary](#)
On Wednesday 6/26/2019 at approximately 15:10, I, Inspector Emily Waldron, and Inspector Lou Colby conducted a joint field/stormwater/reclamation inspection at Sandridge Exploration & Production LLC Refuge 0780 S16 451456 in Jackson County Colorado. While there, we observed a shut-in location.
During this inspection the following possible compliance issues were observed:
Non-reportable spill - stained soil on location. See photo 3. Comply with Rule 603.f and control and contain spills/releases and clean up per Rule 906.a by 8/2/2019.
Parts from containment around triplex pump have become debris. See photo 1. Comply with Rule 603.f by 8/2/2019.
Equipment stored on location. Unused equipment on location. See photo 2. Comply with Rule 603.f by 8/2/2019.
Site degradation occurring. See photo 4. All location stormwater BMPs need maintenance. Install or repair required BMPs per Rule 1002.f by 8/2/2019.
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report 689802876.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	405-429-5974, 911	Date:	
Corrective Action:			

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Equipment stored on location. Unused equipment on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/02/2019
Type	OTHER		
Comment:	Non-reportable spill - stained soil on location.		
Corrective Action:	Comply with Rule 603.f . Control and contain spills/releases and clean up per Rule 906.a.	Date:	08/02/2019
Type	DEBRIS		
Comment:	Parts from containment around triplex pump have become debris.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/02/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 451455 Type: WELL API Number: 057-06601 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Access road through hay fields was underwater 6/19/2019, Sandridge was informed in the field on 6/19 that was a major stormwater issue. Heavy precipitation and irrigation continued through the weekend and on 6/26/2019 and 6/27/2019 Sandridge was observed adding fresh material to roadway without any stormwater controls. On 6/26 and 6/27 Sandridge was informed that every truck driving that road while it had no stormwater BMPs was out of compliance with Rule 324A.a. and 1002.f.](#)

[Site degradation occurring. All location stormwater BMPs need maintenance.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402096781	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4868735
689802877	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4868723