

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/03/2019

Submitted Date:

07/03/2019

Document Number:

696300304**FIELD INSPECTION FORM**

Loc ID 322888 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
		gregory.becker@greeleygov.com	
		COGCCInspections@extracti onog.com	All Inspectors

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
322888	LOCATION	AC			-	Vetting 15-H	AC
449630	WELL	DG	05/18/2018		123-44424	VT-Glenmere C1-16-18	DG

General Comment:

Inspected Facilities

Facility ID: 322888 Type: LOCATION API Number: - Status: AC Insp. Status: AC

CompletionOperation: Drillout

Date Flowback:

Contractor: Patriot Well Services

Comment: Simultaneous Drillout operations taking place at the time inspection. Ensign 135 is performing concurrent Drillout on the same pad. Fluids and Solids are being managed by Bullseye Testing, utilizing Green Completion well testing configuration.

Corrective Action: Chemical not in secondary containment, Repair or install berms or other secondary containment devices per Rule 906.d.(1).
Generator not grounded, crew working on getting it grounded

Date: 07/08/2019

Facility ID: 449630 Type: WELL API Number: 123-44424 Status: DG Insp. Status: DG

CompletionOperation: Drillout

Date Flowback:

Contractor: Patriot Well Services

Comment: Simultaneous Drillout operations taking place at the time inspection. Ensign 135 is performing concurrent Drillout on the same pad. Fluids and Solids are being managed by Bullseye Testing, utilizing Green Completion well testing configuration.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday, 07.03.2019 at approximately 10:43 AM, I, Inspector Erica Petrie, conducted a Field Inspection at Extraction Oil and Gas, Vetting 15-H Pad, at (Location #322888 in Weld County, Colorado.</p> <p>While there, I observed Type of Operation: Drillout, Flowback</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Generator not ground, Crew had stated generator had just been replaced, and they will get it ground ASAP.</p> <p>Chemical not inside secondary containment, crew working on getting containment.</p> <p>Repair or install berms or other secondary containment devices per Rule 906.d.(1).</p> <p>I spoke with Phil Link, Completion Supervisor with Extraction Oil and Gas. Phil stated the generator had just recently been replaced and crew would get it ground. And also have the crew get the chemical into the secondary cont</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if corrective actions are identified).</p> <p>This is a summary of inspection report.</p>	petrie	07/03/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402097035	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869100

696300305	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869099
-----------	--------	---

