

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/02/2019

Submitted Date:

07/03/2019

Document Number:

696600239

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
324270 \_\_\_\_\_ Wentzel, Dougo \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 11 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Clark, Chris		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>
, DNR		dnr_cogccengineering@state.co.us	<a href="#">All Engineering</a>
Peicka, Conor		conor.pesicka@state.co.us	<a href="#">All Inspections</a>
Kellerby, Shaun		shaun.kellerby@state.co.us	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266869	WELL	SI	09/01/2009	GW	045-09853	SOUTH SHALE RIDGE 1-14H	SI

**General Comment:**

This is a follow up inspection from [Doc#696600089](#) .Dated 6/6/19 Required Corrective Action (s) items noted in previous inspections have not been satisfied.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	Battery sign posted on gas meter		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	911/970-858-8550		
Corrective Action:			Date:

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Debris and weeds and on location, and in tank containment berm		
Corrective Action:	Comply with Rule 603.f .		Date: 07/15/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:			Date:

Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 266869 Type: WELL API Number: 045-09853 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well last produced Aug 2009.  
No current MIT on record or delinquent as required by Rule 326  
Last MIT on 2/6/15 Doc#400796903.

Corrective Action: Contact dnr\_cogccengineering@state.co.us with resolution plan.

Date: 07/15/2019

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail					
Compaction	Fail					
		Gravel	Pass			
		Compaction	Pass			
Gravel	Pass					

**Comment:** Corrective actions have not been made.  
 Stormwater erosion not being controlled on the location at this time.  
 BMP's need repaired or are not being maintained at this time. Waddles have sediment moving over the top of them at entrance. No BMP to prevent erosion off surface of location.  
 Erosion is evident along un-stabilized slope at the east side of location .  
 Storm Water Erosion moving off the East side location and down the access road

**Corrective Action:** Install or repair required BMPs per Rule 1002.f.

Date: 03/29/2019

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On (Tuesday) (7/2/19) at approximately (1113), I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Re-Inspection) at (Maralex) (South Shale Ridge 1-14H), (API #045-09853) in (Mesa) Colorado. While there, I observed (A Production Operation only.) During this inspection compliance issues were observed: All corrective actions have not been made from previous inspection. Stormwater erosion not being controlled on the location at this time. BMP's need repaired or are not being maintained at this time. Weeds and debris on location No current MIT on record or delinquent as required (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	07/02/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402095634	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4868168">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4868168</a>
696600244	Photo log inspection 696600239 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4868095">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4868095</a>