

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/02/2019

Submitted Date:

07/03/2019

Document Number:

696600248**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 312541 Wentzel, Dougo 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
, Caerus		COGCC.inspections@caerus oilandgas.com	All inspection

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221881	WELL	SI	06/01/2018	GW	077-08483	DEBEQUE 1-8	PR

General Comment:[Routine FIU General Field Inspection](#)

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:	No Tank Battery sign at tank battery or entrance.			
Corrective Action:	Install sign to comply with Rule 210.b			Date: 08/02/2019
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/ 970-285-2615 and 970-301-1319 on tanks			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unused equipment on location at wellhead			
Corrective Action:	Comply with Rule 603.f .			Date: 08/02/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	TANK BATTERY			
Comment:				
Corrective Action:				Date:
Type	SEPARATOR			
Comment:				

Corrective Action:		Date:	
Equipment:		corrective date	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	221881	Type:	WELL	API Number:	077-08483	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Compaction	Pass					
		Compaction	Pass			
Gravel	Pass					
		Gravel	Pass			

Comment: [At time of inspection stormwater erosion appears to be controlled.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On (Tuesday) (7/2/19) at approximately (1413), I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Inspection) at (Caerus) (Debeque 1-8), (API #077-08483) in (Mesa) Colorado. While there, I observed (A Production Operation only.) During this inspection compliance issues were observed: No Tank Battery sign posted Unused equipment on location. (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	07/02/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402095652	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4868182
696600249	Inspection 696600248 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4868149