

# Inspection Photos

API: 05-009-06134

Operator: SAMSON OIL COMPANY

Inspection Date: 7/9/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-009-06134 | Date: 7/9/2019

## Inspection Photos



**Photo 1.** Pipe riser located 390 feet northeast of well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06134 | Date: 7/9/2019

## Inspection Photos



**Photo 2.** Facing north toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06134 | Date: 7/9/2019



## Inspection Photos



**Photo 3.** There is a degraded fence that remains around the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06134 | Date: 7/9/2019

## Inspection Photos



**Photo 4.** There is a bare area approximately 70'x70'.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06134 | Date: 7/9/2019



## Inspection Photos



**Photo 5.** There is a second pipe riser 150 feet north of the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06134 | Date: 7/9/2019