

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2019

Submitted Date:

07/10/2019

Document Number:

687905108**FIELD INSPECTION FORM**
 Loc ID 325560 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
,	970-563-4000	maralextech@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215004	WELL	PR	08/28/2006	GW	067-06609	HEIKKINEN 1-10	PR

General Comment:

This is a follow inspection to the previous inspection Doc#687904763. This inspection does not allieviate prior corrective actions. Corrective actions that have been completed will be noted on this report. Photos of location are at the end of this report.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds need to be controlled around equipment.		
Corrective Action:	Comply with Rule 603.f.		Date: 06/16/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:	Wildlife bird netting on top of tank still has holes and needs to be repaired or replaced.					
Corrective Action:	Comply with Rule 324 A.a.				Date:	05/23/2019

Paint

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berm has been built up around produced water tank and is compacted and sufficient and passes re-inspection.			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>

Venting:

Yes/No	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Flaring:

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Inspected FacilitiesFacility ID: 215004 Type: WELL API Number: 067-06609 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905109	Weeds around equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874937
687905110	Berm Repaired.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874938
687905111	Wildlife netting repair or replace.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874939