

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2019

Submitted Date:

07/10/2019

Document Number:

687905112**FIELD INSPECTION FORM**
 Loc ID 311955 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|---------------------------------|
| , | 970-563-4000 | maralextech@gmail.com | All Inspections |
| Ferrin, Jeremy | | jeremy.ferrin@state.co.us | |
| Labowskie, Steve | | steve.labowskie@state.co.us | |

General Comment:

This is a follow up inspection from the previous inspection doc#687904769. This inspection does not allieviate corrective actions from previous inspection.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

| | | | |
|--------------------|--|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused wellhead valve that was sitting on pumpjack skid has been removed. | | |
| Corrective Action: | | Date: | |
| Type | WEEDS | | |
| Comment: | Weeds around separator need to be controlled and CA from previous inspection#687904769 has not been completed. | | |
| Corrective Action: | Comply with Rule 603.f. | Date: | 06/16/2019 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|---------------------------|--|-------|-----------------|
| Type: Pump Jack | # 1 | | corrective date |
| Comment: | #3B gearbox on pumpjack is still leaking from previous inspection#687904769 and CA has not been completed. | | |
| Corrective Action: | Comply with Rule 1002.f.(2) | Date: | 06/16/2019 |
| Type: Pump Jack | # 1 | | |
| Comment: | #1 pumpjack exhaust oily waste from previous inspection# 687904769 has not been completed. | | |
| Corrective Action: | Comply with Rule 907.e. and 1002.f.(2) | Date: | 06/16/2019 |
| Type: Ancillary equipment | # 2 | | |
| Comment: | Stained gravel/soil around wellhead has not been removed from prior CA inspection#687904769 | | |
| Corrective Action: | Comply with Rule 907.e. and 1002.f.(2) | Date: | 06/16/2019 |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| | | | | Material Handling And Spill Prevention | Fail | |

Comment: [Spill prevention for engine oil day tank is sitting on location but has not been put in use. CA from previous inspection#687904769 has not been completed.](#)

Corrective Action: [Comply with Rule 1002.f.\(2\)B](#)

Date: 06/16/2019

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------------|---|
| 687905113 | Spill prevention not in use. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874940 |
| 687905114 | Exhaust oily waste | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874941 |
| 687905115 | Stained gravel around wellhead. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874942 |
| 687905116 | Wellhead valve removed from skid. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874943 |
| 687905117 | Weeds around equipment | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874944 |
| 687905118 | Gearbox leak. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4874945 |