

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/10/2019

Submitted Date:

07/11/2019

Document Number:

696200372

FIELD INSPECTION FORM

Loc ID 313671 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
OGCC Operator Number: 10657
Name of Operator: PCR OPERATING LLC
Address: 4040 BROADWAY STREET #510
City: SAN ANTONIO State: TX Zip: 78209

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		dkunovic@passcreekresources.com	
		gwehrer@passcreekresources.com	
		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224819	WELL	PR	10/01/2018	GW	087-05206	NICHOLS 3	RI

General Comment:

This is a follow-up good housekeeping inspection.

This inspection is to document compliance for the following corrective actions:

210.b: Install sign to comply with Rule 210.b
603.f: Comply with Rule 603.f (Weeds).

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Sign at wellhead has been updated with correct information in accordance with 210.b. This corrective action has been addressed.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	_____

Good Housekeeping:

Type	WEEDS		
Comment:	<p>Previous inspection documented noxious weeds (Canada thistle, Cirsium arvense) on the location and required operator to conduct weed management.</p> <p>Sufficient and ongoing weed management does not appear to be occurring; Canada thistle remains evident at well and location. Additionally Musk thistle (Carduus nutans) is evident on the location. Weedy vegetative growth has established/accumulated around the well and production equipment; This is considered a fire hazard and needs to be removed.</p> <p>Original corrective action has not been addressed and remains applicable.</p>		
Corrective Action:	Comply with Rule 603.f. Ongoing weed management and monitoring is required, and needs to occur in accordance to COGCC rules and regulations.		Date: <u>05/25/2019</u>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 224819 Type: WELL API Number: 087-05206 Status: PR Insp. Status: RI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696200373	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4875910