

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2019

Submitted Date:

07/11/2019

Document Number:

687905140**FIELD INSPECTION FORM**
 Loc ID 306805 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	970-563-4000	maralextech@gmail.com	All Inspections
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267561	WELL	PR	08/05/2003	GW	067-08800	MOLLIE CORYNNE 33-7-2 2A	PR

General Comment:

This is a follow up inspection from previous inspection doc#687904798. This inspection does not allieviate corrective actions from prior inspections performed. Any completed corrective actions will be noted in this report. Photos are at the end of this inspection report.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment parts sitting on concrete and plastic tub out front of fence has been removed.		
Corrective Action:		Date:	
Type	TRASH		
Comment:	Used rags and pads around equipment.		
Corrective Action:	Clean up trash and dispose of properly per Rule 603.f.	Date:	06/01/2019
Type	WEEDS		
Comment:	Weeds and dead brush around equipment are controlled.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:	Pumpjack gearbox seals that were leaking gear oil down unit and on concrete on both the east and west side of unit appear to have been repaired and oily waste cleaned up.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead is leaking from packing gland or oil box.		
Corrective Action:	Repair/maintain wellhead per Rule 1002.f.(2)	Date:	05/29/2019

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 267561 Type: WELL API Number: 067-08800 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905141	Weeds controlled and unused equipment removed.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876072
687905142	Gearbox seal repaired east side.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876073
687905143	Leaking wellhead packing gland or oil box.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876074
687905144	Gearbox seal repaired west side.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876075