

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/02/2019

Submitted Date:

07/05/2019

Document Number:

689703266**FIELD INSPECTION FORM**Loc ID 335674 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 11 Number of Comments
- 2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Chollett, Shannon		shannon.chollett@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only
Fischer, Alex		alex.fischer@state.co.us	
Arauza, Steven		steven.arauza@state.co.us	
Burger, Craig		craig.burger@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
360	WELL	PR	09/20/2008	GW	045-15486	N. PARACHUTE EF12B-DX D31 59	PR
362	WELL	PR	09/21/2008	GW	045-15487	N. PARACHUTE EF11C D31 595	PR
292255	WELL	PR	09/17/2008	GW	045-14664	N. PARACHUTE EF 12A D31 595	PR
292256	WELL	PR	06/01/2018	GW	045-14663	N. PARACHUTE EF11D D31 595	PR
292258	WELL	PR	09/17/2008	GW	045-14665	N.PARACHUTE EF14B D31 595	PR
292259	WELL	PR	09/17/2008	GW	045-14661	N. PARACHUTE EF14A D31 595	PR
292260	WELL	PR	09/18/2008	GW	045-14660	N. PARACHUTE EF12D D31	PR
292261	WELL	PR	09/18/2008	GW	045-14659	N. PARACHUTE EF12C D31 595	PR

**General Comment:****COGCC Inspection Report Summary**

On Tuesday 07/02/2019 at approximately 1100 hours, I, Inspector Mike Longworth, conducted a Follow up inspection to inspection doc # 689703156 at Caerus, Pad D31, Location # 335674, in Garfield County, Colorado.

Inspected Facilities						
Facility ID:	360	Type:	WELL	API Number: 045-15486	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	<p>Gas bubbling in cellar.            Caerus has been in communication with COGCC Engineering Staff and issue has been handed over to COGCC Environmental Staff. Further corrective actions were made from Enironmental Staff:            "The COGCC agrees with signage added to the entrance of the Location and at the well heads"            No signage found for requested requirement</p> <p>By July 12, 2019 Submit ALL analytical for gas and fluid samples (if collected) from all wells at Location 335674 via a Form 43.            Submit the information that Mr. Tompkins provided via email on a Sundry Form 4 for API's 05-045-14659 and 05-045-15486 to the attention of Shannon Chollett and Steven Arauza and provide to them the Sundry Document Numbers.            Inspectors review of well file found no documents in the documents file or in document review.</p>					
Corrective Action:	<p>Install signage at the entrance of location and at the well heads.            Provide COGCC Environmental Staff with documentation and Forms requested</p>					Date: 07/12/2019
Facility ID:	362	Type:	WELL	API Number: 045-15487	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	292255	Type:	WELL	API Number: 045-14664	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	292256	Type:	WELL	API Number: 045-14663	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	292258	Type:	WELL	API Number: 045-14665	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	292259	Type:	WELL	API Number: 045-14661	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	292260	Type:	WELL	API Number: 045-14660	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:						Date:

<b><u>Producing Well</u></b>			
Comment:	Producing well		
Corrective Action:		Date:	
Facility ID: <u>292261</u> Type: <u>WELL</u> API Number: <u>045-14659</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	<p>Cellar has been dug up for trouble shooting. No visable leak observed.            Caerus has been in communication with COGCC Engineering Staff and issue has been handed over to COGCC Environmental Staff. Further corrective actions were made from Enironmental Staff:            "The COGCC agrees with signage added to the entrance of the Location and at the well heads"            No signage found for requested requirement</p> <p>By July 12, 2019 Submit ALL analytical for gas and fluid samples (if collected) from all wells at Location 335674 via a Form 43.            Submit the information that Mr. Tompkins provided via email on a Sundry Form 4 for API's 05-045-14659 and 05-045-15486 to the attention of Shannon Chollett and Steven Arauza and provide to them the Sundry Document Numbers.            Inspectors review of well file found no documents in the documents file or in document review.</p>		
Corrective Action:	Install signage at the entrance of location and at the well heads. Provide COGCC Environmental Staff with documentation and Forms requested		Date: <u>07/12/2019</u>

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Open hole behind meter sheds has been back filled.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402097456	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869391">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869391</a>
689703278	Inspection 689703266 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869390">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869390</a>