

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/11/2019

Submitted Date:

07/12/2019

Document Number:

694900047

FIELD INSPECTION FORM

Loc ID 335300 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

- 18 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, vanguard		scollett@vnrenergy.com	
, vanguard		sgahn@vnrenergy.com	SR. EH&S
, vanguard		aaxelson@vnrenergy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264260	WELL	PR	07/27/2016	GW	045-08134	BRYNILDSON 14C - 20 - 692	PR
276111	WELL	PR	02/13/2012	GW	045-10428	BRYNILDSON 14B-20-692	PR
276112	WELL	PR	07/28/2009	GW	045-10427	BRYNILDSON 13A-20-692	PR
276113	WELL	PR	06/08/2009	GW	045-10426	BRYNILDSON 14D-20-692	PR
298340	WELL	PR	06/04/2009	GW	045-17144	BRYNILDSON 24C-20-692	PR
298341	WELL	PR	06/08/2009	GW	045-17145	BRYNILDSON 24B-20-692	PR
298342	WELL	PR	06/03/2009	GW	045-17146	BRYNILDSON 14A-20-692	PR
298343	WELL	PR	06/08/2009	GW	045-17147	BRYNILDSON 24A-20-692	PR
298344	WELL	PR	06/08/2009	GW	045-17148	BRYNILDSON 23A-20-692	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type UNUSED EQUIPMENT

Comment: tank at wellheads not being used/no labels see photos

Corrective Action: Comply with Rule 603.f .

Date: 08/15/2019

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: livestock fence

Corrective Action:

Date:

Type SEPARATOR

Comment: hog panel

Corrective Action:

Date:

Equipment:

corrective date

Type: Horizontal Heated Separator # 9

Comment:

Corrective Action:

Date:

Type: Emission Control Device # 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment: chemical tank

Corrective Action:

Date:

Type: Bird Protectors # 8

Comment:

Corrective Action:

Date:

Type: Plunger Lift # 9

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	500 BBLs	STEEL AST		,
Comment: centralized battery					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES
Comment:	braden heads open
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	264260	Type:	WELL	API Number:	045-08134	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift				Date:				
Corrective Action:					Date:				
Facility ID:	276111	Type:	WELL	API Number:	045-10428	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift				Date:				
Corrective Action:					Date:				
Facility ID:	276112	Type:	WELL	API Number:	045-10427	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift				Date:				
Corrective Action:					Date:				
Facility ID:	276113	Type:	WELL	API Number:	045-10426	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift				Date:				
Corrective Action:					Date:				
Facility ID:	298340	Type:	WELL	API Number:	045-17144	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift				Date:				
Corrective Action:					Date:				
Facility ID:	298341	Type:	WELL	API Number:	045-17145	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift				Date:				
Corrective Action:					Date:				
Facility ID:	298342	Type:	WELL	API Number:	045-17146	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift				Date:				
Corrective Action:					Date:				
Facility ID:	298343	Type:	WELL	API Number:	045-17147	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift				Date:				
Corrective Action:					Date:				

Facility ID: 298344 Type: WELL API Number: 045-17148 Status: PR Insp. Status: PR

Producing Well

Comment: [plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 7/11/19 at approximately 2:00 PM, I, Inspector Scott Ramsey, conducted a field inspection at Vanguard Brynildson 14C, at Location #335300 in Garfield County, Colorado. While there, I observed Normal production operations. During this inspection the following possible compliance issues were observed: Possible chemical tank at well heads not hooked up to anything and is empty. Unused equipment, weeds, waste, and trash requirements. Refer to photograph of observed compliance issue A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	ramseys	07/11/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900048	694900047	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876261