

Inspection Photos
Location Name: GECKO 12-18
API#: 05-071-07712
INSP. #: 695101011



PHOTO 1: WELLHEAD

PHOTO 2: WELL SIGN

Inspection Photos
Location Name: GECKO 12-18
API#: 05-071-07712
INSP. #: 695101011



PHOTO 3: NO DITCHING OR BERMING ON ROW TO PREVENT STORMWATER POOLING ON ROW AND ROW SURFACE MATERIAL FROM MIGRATING OFF OF ROW AND BEYOND ORIGINAL ROW DISTURBANCE AREA. **INSTALL OR REPAIR BMP'S TO PREVENT STORMWATER POOLING ON ROW AND TO PREVENT ROW SURFACE MATERIAL FROM MIGRATING OFF OF ROW IN ACCORDANCE WITH RULE 1002.f. CA DATE 9/12/19.**

PHOTO 4: CLOSER VIEW FROM PREVIOUS PHOTO (PHOTO 3). PHOTO SHOWING STORMWATER POOLING ON ROW AND EROSION OF ROW SURFACE MATERIAL OFF OF ROW.

Inspection Photos
Location Name: GECKO 12-18
API#: 05-071-07712
INSP. #: 695101011



PHOTO 5: CLOSER VIEW OF ROW EROSION AND ROW SURFACE MATERIAL MIGRATION OF ORIGINAL ROW DISTURBANCE AREA FROM THE PREVIOUS 2 PHOTOS (PHOTO'S 3 & 4).

PHOTO 6: ANOTHER AREA APP. 200 YARDS SOUTH FROM PREVIOUS PHOTOS OF NO DITCHING OR BERMING ON ROW TO PREVENT STORMWATER CAUSING ROW SURFACE MATERIAL TO MIGRATING OFF OF ROW AND BEYOND ORIGINAL ROW DISTURBANCE AREA. **INSTALL OR REPAIR BMP'S TO PREVENT STORMWATER POOLING ON ROW AND TO PREVENT ROW SURFACE MATERIAL FROM MIGRATING OFF OF ROW IN ACCORDANCE WITH RULE 1002.f. CA DATE 9/12/19.**

Inspection Photos
Location Name: GECKO 12-18
API#: 05-071-07712
INSP. #: 695101011



PHOTO 7: CLOSER VIEW OF EROSION FROM THE PREVIOUS PHOTO (PHOTO 6).

PHOTO 8: VIEW OF SAME EROSION FROM PREVIOUS 2 PHOTOS (PHOTO'S 6 & 7). FROM THE OPOSITE SIDE (SOUTH VIEW).

Inspection Photos
Location Name: GECKO 12-18
API#: 05-071-07712
INSP. #: 695101011



**PHOTO 9: NATURAL DRAIN UPSLOPE FROM ROW EROSION
AREA WITH NO BMP'S IN PLACE.**