

Inspection Photos
Location Name: TURKEY 24-7
API#: 05-071-06574
INSP. #: 695101013



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN



Inspection Photos
Location Name: TURKEY 24-7
API#: 05-071-06574
INSP. #: 695101013



PHOTO 3: AREA OF EROSION ON MAIN ROW NORTH OF LOCATION TOWARD THE BOTTOM OF THE HILL. REPAIR EROSION AND REPAIR OR INSTALL BMP'S TO PREVENT EROSION AND COMPLY WITH RULE 1002.f. CA DATE 8/12/19

PHOTO 4: CLOSER VIEW OF EROSION FROM PREVIOUS PHOTO (PHOTO 3).