

Inspection Photos

Loc#416625

Operator: Sandridge

Inspection Number: 692401136

Inspection Date: 6/26/19





Photo#1:
Overviews of Location.

June 26, 2019



Photo#2:
View from top of stockpile pile to Northwest.



Photo#3:
View along unstable stockpile pile perimeter.

June 26, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Surprise Damfino Loc#416625



Photo#4:
View of unstable stockpile to Southeast.




Photo#5:
View along base of unstable stockpile to Northwest.

June 26, 2019



Photo#6:
Cracking, sloughing, erosion of stockpile.




Photo#7:
Cracking, sloughing, erosion of stockpile.

June 26, 2019



Photo#8:
Point along base of stockpile where silt fence has Failed.



Photo#9:
Point along base of stockpile where silt fence has Failed.

June 26, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Surprise Damfino Loc#416625



Photo#10:
South or Location side of stockpile, no BMPs;
run-on and degradation occurring.



Photo#11:
South or Location side of stockpile, no BMPs;
run-on and degradation occurring.

June 26, 2019



Photo#12:
Cut at Southwest corner of site; sloughing/erosion evident.



Photo#13:
Cut at Southwest corner of site; sloughing/erosion evident.

June 26, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Surprise Damfino Loc#416625



Photo#14:
Stormwater is improperly ponding on East side of site.

June 26, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Surprise Damfino Loc#416625