

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/05/2019

Submitted Date:

07/05/2019

Document Number:

696600250**FIELD INSPECTION FORM**
 Loc ID 312531 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Clark, Chris		cogccnotifications@laramie-energy.com	All Inspections
Burger, Craig		craig.burger@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
, DNR		dnr_cogccengineering@state.co.us	All Engineering

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221861	WELL	SI	12/01/2018	GW	077-08463	ANDERSON 1	TA

General Comment:[This is a follow up inspection from doc#696600019 Dated 5/3/19](#)

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-248-0497 Dispatch 970-242-1234

Corrective Action:

Date:

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Storage of unused equipment on location. Riser needs Locked Out /Tagged Out		
Corrective Action:	Comply with Rule 603.f .	Date:	08/06/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 221861 Type: WELL API Number: 077-08463 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment:

Temporarily Abandoned

Wellhead cellar has water in it. Bubbles are seen coming to surface outside of casing, with H2S gas reading at 1.8 ppm and LELS on meter going as high as 9 at time of inspection.

Well had a Braded head test 5/1/19

Shut in pressure at start 3.5 lbs

Blew to zero in 10 seconds

5min 0

10 min 0

15 min 0

20 min 0

25 min 0

30 min 0

Corrective Action: [Contact dnr_cogccengineering@state.co.us](mailto:dnr_cogccengineering@state.co.us) with resolution plan.Date: 07/15/2019

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gradient Terraces	Pass					
		Gravel	Pass			
Gravel	Pass					
		Compaction	Pass			
Compaction	Pass					

Comment: [At time of inspection stormwater erosion appears to be controlled.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On (Friday) (7/5/19) at approximately (0923), I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Re-Inspection) at (Laramie) (077-08463), (API #077-08463) in (Mesa) Colorado. While there, I observed (A Production Operation only.) During this inspection compliance issues were observed: Bubbles surfacing from inside of cellar ring around the wellhead. Stored un-used equipment on location. Riser not locked Out / Tagged Out. (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	07/05/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402098258	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4870366
696600251	Inspection 696600250 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4870339